CERTIFICATE OF COMPLIANCE

Certificate Number	20190402-E466402
Report Reference	E466402-20140118
Issue Date	2019-APRIL-02

Issued to:	ESTUN AUTOMATION CO LTD 155 JIANG JUN RD S JIANGNING DEVELOPMENT ZONE NANJING JIANGSU 211100 CHINA
This certificate confirms that representative samples of	COMPONENT - SERVO AND STEPPER MOTORS See Addendum Page
	Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.
Standard(s) for Safety:	UL 1004-1, Rotating Electrical Machines - General Requirements UL 1004-6, Servo and Stepper Motors CSA C22.2 No. 100, Motors and Generators
Additional Information:	See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number 20190402-E466402
Report Reference E466402-20140118
Issue Date 2019-APRIL-02

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

EMJ-04A□B□□-UL, EMJ-04A##&&-*, EMJ-08A□B□□-UL, EMJ-08A##&&-*, EMJ-10A□B□□-UL, EMJ-10A##&&-*, EMG-10A□B□□-UL, EMG-10A##&&-*, EMR-10A##&&-*, EMG-15A□B□□-UL, EMG-15A##&&-*, EMR-15A##&&-*, EMG-20A□B□□-UL, EMG-20A##&&-*, EMR-20A##&&-*, EMT2-200GW-LAVA30-001, EMT2-200HW-LAVA30-001/002, EMT-070DRA11-01, EMG-50A□A□□-UL, EMG-50A##&&-*, EMR-50A##&&-*, EMG-30A□A□□-UL, EMG-30A##&&-*, EMR-30A##&&-*, EMJ-02A□A□□-UL, EMJ-02A##&&-*, EMJ-08BPB□□-UL, EMJ-08B##&&-*, EMJ-04BPB□□-UL, EMJ-04B##&&-*, EMJ-02BPA□□-UL, EMJ-02B##&&-*, EM3A-A5A##&&&-*, EMR-A5A##&&&-*, EM3A-01A##&&&-*, EMR-01A##&&&-*, EM3A-02A##&&&-*, EMR-02A##&&&-*, EM3A-04A##&&&-*, EMR-04A##&&&-*, EM3A-08A##&&&-*, EMR-08A##&&&-*, EM3A-10A##&&&-*, EMR-01A##&&&-*

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/